



Seminar series Welding Power Sources

Service QINEO / Quinto
QN-TR-SE

CLOOS

Weld your way.

www.cloos.de

Seminar series

Welding power sources

Service QINEO / Quinto

This seminar is for service and maintenance staff. Learn everything about maintenance, fault finding and repair work of welding power sources. Among others, you get familiar with the basic functions of the operation and learn how to explain the interplay of the components, to find and repair the error causes.

Content

- Learn everything about the basic functions of the operation.
- Get familiar with the structure of welding power sources.
- Explain the functions and the interplay of the components.
- Find and repair the error causes.
- Exchange the component groups (e.g. boards, power supplies, fuses).
- Take preventive maintenance measures.

Target group

- Users who are in charge of maintenance, fault finding and repair work of welding power sources
- Service and maintenance staff

QN-TR-SE



Seminar period

1 day

Seminar times

Monday: 09:00 - 16:30

Tuesday to Thursday:

08:00 - 16:30

Friday: 08:00 – 12:00 a.m.

Participants

Small groups up to a maximum of 4 persons

Conditions

- Vocational education in the electrical engineering
- Certificate "Qualified electrician" acc. to VDW 0100
- Education as qualified electrician.